

MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY BREATH ALCOHOL PROGRAM

RECEIVED
By Carol Day at 10:54 am, May 28, 2013

CMI INTOXILYZER 5000 MAINTENANCE REPORT

REPORT #4

マ語語 CIVII	INTON	ILIZEN JUUU	MAINT	MAINCE IN	FLOUI					REPURI#	
Complete this repo Complete this repo Retain the original	ort whene	ver the instrume	nt is service	ed or repaire	d and wh	enever it is p	olaced into servi				
INTOXILYZER 5000 SN 66 003441							DATE OF INSPECTION 05/25/2013				
LOCATION OF INSTRUMENT (STREET AND CITY)						··· · · · · · · · · · · · · · · · · ·	TIME OF INSPECTION				
711 N. Main St. Grain Valley							2:51 am				
			ound to be	satisfactory o	or is oper	pperating within established limits. (Write in observed values					
where determined.) Unmarked items must be corrected before using instrument.											
☑ DIAGNOSTIC CHECK (PRINTOUT ATTACHED) DATE AND TIME (FROM PRINTOUT) 05/25/13 02:53											
CHARACTER DISPLAY TEST											
PRINT TEST	(PRINTO	UT ATTACHED)			· · · · · · · · · · · · · · · · · · ·						
SIMULATOR S	SOLUTIO	N SUPPLIER G	uth Labor	atories Inc.		LOT # <u>_1</u>	2040	_ EXP. DA	TE_03/07/20	014	
SIMULATOR T	EMPERA	TURE (34°C ± 0	.2°C)	34.0°	SIM	JLATOR SN	SD 1434	EXP. DA	те <u>04/11/2</u> 0	014	
☑ CALIBRATION CHECK (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT)											
Run three tests using a standard solution. All three tests must be within \pm 5% of the standard value and must have a spread of .005 or less. Mark the box corresponding to the standard solution being used. (PRINTOUT ATTACHED)											
		- MUST READ I									
		- MUST READ I - MUST READ I									
TEST 1 ★ 0.098				TEST 2 ☞ 0.098			TEST 3 ▼ 0.100				
PERFORM RFI TEST (PRINTOUT ATTACHED)											
INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT: (DO NOT INCLUDE SELF-ADMINISTERED TESTS)											
REFUSALS 9	004	1	.0509	1	.1014	3	.1519	2	Over .19	2	
LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR MODIFICATION THAT WAS MADE TO RESTORE THE INSTRUMENT TO OPERATE SATISFACTORILY AND WITHIN ESTABLISHED LIMITS (USE OTHER SIDE IF NECESSARY).											
Meets all Department of Health and Senior Services specifications. When used in a calibrated simulator operating at 34°C +/2°C, this solution will give a breath alcohol analysis instrument reading of 0.100g/210L +/- 3%.											
INSPECTING OFF	ICED 1	; evalvativas attavis saita	ASTVASA (SECTION CO	verkeren konst	Svariori de la co		de vise is a exist was the	HEREST SHEET	-aktistovský filolóf		
SIGNATURE	UER					PRINT FULL NA	ME				
1		Me	2			S. Tracy		!			
TYPE II PÉRMIT NUMBER/EXPIRATION DATE 220305/09-25-2014						TELEPHONE NUMBER (816) 847-6250					
RETURN COMPLETED REPORT TO THE: Breath Alcohol Program, Missouri Department of Health and Senior Services Southeast District Office											
, /				ast District Oi imes Blvd.	nice						
				imes biva. 3luff, MO 639	901						



CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 12040 of
Alcohol Reference Solution for Simulator were analyzed by
gas chromatography on March 9, 2012, using a Perkin Elmer Gas
Chromatograph Autosystem XL S/N: 610N9030209, and found to contain
0.1211% (w/vol) ethyl alcohol. The expiration date for this lot
number is March 7, 2014 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.100 g/210L +/- 3%.

The alcohol and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

NIST Traceability:

Testing was conducted using Cerilliant Reference Standard lot number FN122211-02 whose values are traceable to NIST.

All balances are calibrated annually by an outside agency using NIST traceable weights. Calibration verification is done prior to each use utilizing NIST traceable weights.

THIS SIDE UP/THIS EDGE IN GUTH LABORTORIES, INC. 800-233-2338

711 N. MAIN STREET INTOXILYZER — ALCOHOL AMALYZER MO MODEL 5000 SN 66-003441 05/25/2013

HIR BLANK
OHL CHECK
OHL CHECK
OHL CHECK
OHL CHECK
OHL CHECK
OHL CHECK
OHL CHECK

NO DEL PROGRAT

THIS SIDE UP/THIS EDGE IN GUTH LABORTORIES, INC. 800-233-2338

SM 66-883441 E735-23 IMUALID TEST INHIBITED - RFI

95/25/2913 93:89

ADDITIONAL INFORMATION AND/OR REMARKS SUBJECT'S NAME UMENT LOCATION

TIME FIRST OBSERVED

NT LOCATION

SUBJECT'S NAME

ADDITIONAL INFORMATION AND/OR REMARKS

THIS SIDE UP/THIS EDGE IN GUTH LABORTORIES, INC. 800-233-2338

711 N. MAIN STREET INTOXILYZER - ALCOHOL AMALYZER MO MODEL 5000 SN 66-003441 05/25/2013

DIMONDOTIC TEST

图2.100

PROM CHECK E735,
RAM CHECK
TEMP CHECK
PROCESSOR CHECK
SYNC PULSE
SYNC SPEED
NEG STABILITY
POS STABILITY
REF RANGE M705, 23

PASSED PASSED

PAGGMED PAGGMED PAGGMED PAGGMED

PHOSED

DIFERENTE

FRINTER, CHECK ABCDEFGHIJKLMADPQRSTUUWXYZ 0120456789

THIS SIDE UP/THIS EDGE IN GUTH LABORTORIES, INC. 800-233-2338

SN 66-866441 M735,23

10.100 10

ABCDEFGHIJKLMNOPGRSTUUWXYZ0123A56789

TIME FIRST OBSERVED ADDITIONAL PROFINATION AND/OR REMARKS INSTRUMENT LOCATION

Ļ

TIME FIRST OBSERVED

INSTRUMENT LOCATION

SUBJECT'S NAME

ADDITIONAL INFORMATION AND/OR REMARKS

State of Missouri DEPARTMENT OF HEALTH



PERMIT TYPE II



STEVEN K TRACY

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

INTOXILYZER 5000

for the determination of the alcoholic content of blood from a sample of expired (alveolar) air, issued under the provisions of sections 577.020 through 577.041, RSMo 1986.

09/25/2012	Wante					
Number 220305	Director of State Public Health Laboratory					
xpires 09/25/2014	Marjart V. Brosselly					
•	Director, Department of Health					

MO 580-0771 (7-88)

Lab. 4 (R7-88)